

Chapter 3


Brushless DC motor Drives

Why Brushless DC motor?

- The maximum speed and torque of the Brushed DC Motor is limited by the carbon brush-commutator.
- However, the control of speed and torque of a DC motor is the simplest, because the torque characteristic is linear with i_a and i_f .
- The brushless structure has all the linear characteristics of the brushed DC motor but without the complexity and maintenance requirement of the brush-commutator.

Construction of brushed and brushless DC machines

Brushed DC Motor




Stator - Field



Rotor- Armature

Brushless DC Motor



Stator- Armature




2-poles



4-poles

Rotor- Field

Permanent magnet Brushed and Brushless DC motor




The brush-commutator is replaced by a 3-phase *electronic commutator*, consisting of three Hall sensors for rotor position and a 3-phase inverter.

Permanent magnets for BLDC motor


Neodymium Iron Boron (NdFeB) and Samarium Cobalt

NdFeB: $B_r = 0.8 - 1.4 \text{ T}$; $H_c > 1 \text{ MA/m}$; $\mu_{recoil} \approx 1$; $T_{Curie} = 120 \text{ }^\circ\text{C}$




Remanent flux density or Remanence (B_r) and Coercivity (H_c) field intensity

Three Phase Stator



(a) $\theta = 0^\circ$






(b) $\theta = 150^\circ$

The three-phase stator winding is normally star-connected.


Each phase winding spans 60° (electrical) on each side (i.e., per pole), so the total span for each phase winding is 120° . There are six conductors per pole (i.e., $N_s = 6$) of each winding in 60° spans. The stator windings of each phase are displaced by 120° from its adjacent phase winding.

$$\theta = \int_0^t \omega_m dt + \theta_o$$

The Back EMF Waveform



Phase & line-line voltages



Machine back emf

For the two-pole ($p = 1$) machine, $e = -N_s \frac{d\phi}{dt} = Blv = Blr\omega_m$

$$e_{max} = 2N_s Blv = 2N_s lrB\omega_m \quad \text{V}$$

where l is the active length of the conductors in meters

r is the radius of the stator in meters

ω_m is the rotational speed of the rotor in rad/sec.

B is the air-gap field in Tesla

N_s is the number of conductors per pole


For a star-connected machine with p pole-pairs (i.e., $2p$ poles),

$$e_{max} = 2N_s plrB\omega_m = k'_e \phi_f \omega_m \quad \text{V/phase}$$

$$e_{abmax} = \max(e_a - e_b) = 4N_s plrB\omega_m = k'_E \phi_f \omega_m \quad \text{V}_{\text{line-line}}$$


Inverter drive BLDC machine

The quasi-square three-phase current waveforms can be supplied from the three phase inverter. The three Hall sensor outputs SA - SC are converted into the six switching signals T1 - T6, by the inverter switching logic block.




Ideal motor current waveforms

$$T = \frac{e_a i_a + e_b i_b + e_c i_c}{\omega_m}$$



Inverter switching table

Inverter switching table for $\omega > 0$, or CCW motion




δ	Switches ON	Current flow
$-30^\circ - 30^\circ$	T5, T6	$C+$ and $B-$
$30^\circ - 90^\circ$	T6, T1	$B-$ and $A+$
$90^\circ - 150^\circ$	T1, T2	$A+$ and $C-$
$150^\circ - 210^\circ$	T2, T3	$C-$ and $B+$
$210^\circ - 270^\circ$	T3, T4	$B+$ and $A-$
$270^\circ - 330^\circ$	T4, T5	$A-$ and $C+$

Inverter switching table

Inverter switching table for $\omega < 0$, or CW motion

δ	Switches ON	Current flow
$-30^\circ - 30^\circ$	T5, T6	$C+$ and $B-$
$30^\circ - 90^\circ$	T6, T1	$B-$ and $A+$
$90^\circ - 150^\circ$	T1, T2	$A+$ and $C-$
$150^\circ - 210^\circ$	T2, T3	$C-$ and $B+$
$210^\circ - 270^\circ$	T3, T4	$B+$ and $A-$
$270^\circ - 330^\circ$	T4, T5	$A-$ and $C+$



The developed torque


For a 2-pole machine ($p = 1$)

$$\begin{aligned} T &= 2N_s r l B I \quad \text{Nm/phase} \\ &= 4N_s r l B I \quad \text{Nm} \end{aligned}$$


For a machine with p pole-pairs (i.e., $2p$ poles)

$$T = 4N_s p r l B I = k_T' \phi_f I \quad \text{Nm}$$

Note that the back emf and torque equations of this AC machine are exactly the same as for the brushed DC machine. There are no brushes or commutator. Hence the *name Brushless DC Machine*.




Torque control via DC link current control




Ideally, the DC-link currents (+ve and -ve) should remain constant, at all times. This can be achieved by one DC current regulator, or three separate phase current regulators.

DC link voltage versus speed


Assuming quasi-square phase currents in each winding, via DC-link or phase current controls




$$V_d I_d = 3VI \cos \phi$$



Fourier analysis of phase current



Phase and DC-link current waveforms




Phase current harmonics

$$\begin{aligned}a_n &= \frac{1}{\pi} \int_{-\pi}^{\pi} i \cos(n\omega t) d\omega t \\&= \frac{1}{\pi} \int_{-\pi/3}^{\pi/3} I_d \cos(n\omega t) d\omega t + \frac{1}{\pi} \int_{-\pi}^{-2\pi/3} -I_d \cos(n\omega t) d\omega t + \frac{1}{\pi} \int_{2\pi/3}^{\pi} -I_d \cos(n\omega t) d\omega t \\&= \frac{2I_d}{n\pi} \left[\sin\left(\frac{n\pi}{3}\right) + \sin\left(\frac{2n\pi}{3}\right) \right] \\&= \frac{4I_d}{n\pi} \cos\left(\frac{n\pi}{6}\right) \quad (n=1,3,5)\end{aligned}$$


$$I_1 = a_1 / \sqrt{2} = \frac{4I_d}{\sqrt{2}\pi} \cos\left(\frac{\pi}{6}\right) = \frac{\sqrt{6}I_d}{\pi}$$

$\therefore I_d = \frac{\pi}{\sqrt{6}} I$ where I is the RMS value of the fundamental phase current. Note, I is also the peak value.

Per-phase Phasor diagram



(a)



(b)

(c)

Relationship between V_d and ω_m

$$V \cos \phi = E_f \cos \gamma + IR ; \quad V_d I_d = 3VI \cos \phi = 3IE \cos \gamma + 3I^2 R$$

Noting that $I_d = \frac{\pi}{\sqrt{6}} I$ and cancelling I , $0.427V_d = E \cos \gamma + IR$

When $\gamma = 0^\circ$, $0.427V_d = E + IR = V'_d$ Thus, for small IR , $\omega_m \propto V_d$

V'_d is the per phase RMS voltage supplied to the motor by the inverter.

